

PROPOSED SURFACE DRESSING PROGRAMME 2018 APPENDIX B

plan no	location	location details/comments	length (m)
South Mainland			
S1	A970 North Levenwick to Teevliks	Poor surface texture	510
S2	Levenwick Loop	Poor surface texture	2,460
S3	Teevliks to Bigton (North End)	Worn and fretted.	500
S4	School Junction to Stove X-rds, Sandwich	Time Expired (more than 5 years since overlay)	450
S5	Kirtleside, Sandwich	Time Expired (more than 5 years since overlay)	150
S6	Ringesta, Quendale	Poor SCRIM	890
S7	Brake Road, Quendale	Poor SCRIM	320
S8	Quendale Farm to Hillwell	Poor SCRIM	1,020
S9	Sandwich Waterworks	Public road neglected since Sandwich Phase 2	210
S10	Blett, Cunningsburgh	Cracked, fretted and worn	910
S11	Mid Voxter, Cunningsburgh	Time Expired (more than 5 years since overlay)	660
S12	North Bridge, Cunningsburgh	Cracked, fretted and worn	105
S13	Gulberwick Loop	Poor edges, fretting and small holes	1,885
North Mainland			
N1	A970 Sandwater Overlay	Time Expired (more than 5 years since overlay)	1,050
N2	Wethesta Road (Outer End)	Fretted, worn edges. Dress before deteriorates.	760
N3	Wethersta Industrial Estate	Small "potholes" forming	240
N4	A970 Eela Water to Swinister (2 Sections)	Time Expired (more than 5 years since overlay)	800
N5	B9075 North Skellister Junction to Bretabister Junction	Patched, haunch failures and cracked	3,320
N6	B9076 Voxter (Southtown to Hardwall)	Poor texture.	400
N7	B9078 Burnside to Watch Hill, Eshaness	Fretted, worn edges. Dress before deteriorates.	2,260
N8	Sparl, Brae	Check after breakwater construction	500
N9	Hamar Road, Northmavine	Patching needed in places. Seal with SD.	1,740
N10	Ennisfirth (Inner end only)	Fretted with worn edges.	260
N11	Orbister, Northmavine	Fretted, worn edges. Dress before deteriorates.	910
N12	Assater	Patching needed in places. Seal with SD.	560
N13	Findlin's Farm, Hillswick	Fretted, worn edges. Dress before deteriorates.	330
N14	Barnafield, South Collafirth	Fretted, worn edges. Dress before deteriorates.	380
N15	Firth Road (Junction to Leaside)	Time Expired (more than 5 years since overlay)	590
West Mainland			
W1	Hoganess to Seli Voe Brig	Poor surface texture	1,160
W2	Twatt to Clousta Road at North House Loch	Small holes starting, fretting.	1,150
W3	Clousta Road (Inner End)	Recently patched, dress to seal.	405
W4	Hoganess, Seli Voe	Needs patching in places.	590
W5	B9071 Garderhouse to Red Ayre	Worn, poor surface texture and cracked	2,200
W6	B9071 Laxaburn to Semblister	Poor surface texture	700
W7	West Houlland to Staneyponds	Worn, poor surface texture and cracked	1,200
W8	Riskaness	Needs patching. Double dress inner end?	410
W9	Twatt to Clousta Road (Steep Brae)	Small holes starting, fretting.	565
W10	West Houlland	Time expired, cracked edges.	290
W11	Upper Gruniquoy, Seli Voe	Turning head worn through, seal rest	700
W12	Lower Gruniquoy, Seli Voe	Poor surface texture, in area	120
W13	Skeld Pier Road	Holes and worn from corner to pier.	250
W14	Grindibrek	Poor condition, small holes forming.	70
W15	Reawick Loop Road (Beach to Cemetery)	Fretted with small holes forming in places.	2,300
W16	North Wart, Reawick	Badly worn and cracked in places.	430
W17	Post Office Road, North Wart, Reawick	Badly worn and cracked in places.	120
W18	Red Ayre	Fretted, worn edges. Needs patching.	190
W19	North Lea, Effirth	Worn, dress to seal	350
W20	Silwick (Inner End - last house to shed)	Rest to be overlay resurfacing	135
W21	Westerwick (Inner End and Outer Ends - steep brae)	Rest to be overlay resurfacing	675
W22	A971 Sandness Road (Lungawater to Brunatwatt)	Worn surface with potholes forming	2,600
W23	Reawick Beach Road	Worn and fretting	60

PROPOSED SURFACE DRESSING PROGRAMME 2018 APPENDIX B

plan no	location	location details/comments	length (m)
Central Mainland			
C1	A970 Windy Grind to Veensgarth	Poor SCRIM	1,050
C2	Tingwall Valley	Worn. Starting to fret and pothole in places.	4,440
C3	Kergord Road (North Section)	Time Expired (more than 5 years since overlay)	2,000
Yell			
Y1	Aywick Loop at Corn Hill (DUPLICATE)	Fretted, worn edges and starting to pothole.	560
Y2	A968 Gutcher Hill Bend	Poor SCRIM	180
Y3	B9081 Ulsta to Burravoe (Easter Knowes to Loch o' Uls)	Poor texture, SD to seal patches.	1,075
Y4	B9081 High Road, Yell (North End)	Time Expired (more than 5 years since overlay)	2,400
Y5	Otterswick to South Aywick	Worn. Starting to fret in places.	1,400
Y6	North Aywick to Hogalee Burn	Worn. Starting to fret in places.	465
Unst			
Lerwick			
L1	Sea Road to Seafield	Time Expired (more than 5 years since overlay)	390
L2	Blackhill Industrial Estate, 6mm	Worn, SD to seal.	260
L3	Shetland Marts	Worn and starting to fret.	355
L4	Seafield Road, 6mm	Time Expired (more than 5 years since overlay)	170
Bressay			
B1	Heogan Road - Inner End (2nd Grid to Gut Factory)	Worn with some repairs needed in haunches.	500
B2	Heogan Road - Middle (Gardie to 1st Grid)	Worn edges, overlay patching needed in sunk parts.	750
B3	Voehead to Mail Crossroads	Fretted centre joint and generally open texture.	1,130
B4	Mail Crossroads to Kirkabister	Worn in places. Treat all this year.	3,105
B5	Kirkabister Ness (Grid to Lighthouse)	Part time expired, patching needed at south end.	385
B6	Gunnista Road (School to Gunnista Junction)	Worn with small potholes starting to form.	2,090
B7	Uphouse Brae (Mail to Setter Junction)	Small holes, patched and worn. Dress to seal.	1,150
B8	Heogan Gunnista Link Road	Fretted, dress before further deterioration.	280
B9	Ferry Terminal to Heogan Junction	Worn with small potholes starting to form.	460
B10	Beosetter	Worn, patching and passing places to be sealed.	1,140
B11	Manse Road (Mizpah House)	Patched starting to fret so needs to be sealed.	180
B12	Old Post Office Road	Seal edges of existing patches.	95
B13	Brough (Outer End)	Worn. Inner end to be resurfaced.	200
B14	Pettifirth	Patched with more haunch repairs needed. Seal.	1,560
B15	East Ham (to turning head)	Generally worn.	180
B16	South Ham	Time expired. Weeds in road need treated.	440
B17	Upper Glebe	Potholes at inner end/car park to be repaired.	95